



Fix for Virtual Setup and A-Axis Enable Boxes Not Showing in Control Panel v2.1

If you have installed the Shark Control Panel v2.1 software and do not see the check boxes to enable the Virtual Setup and the A-Axis when the control panel page opens this is a possible fix to the problem if it is caused by the computer display.




Screen shot of what you might see if you have this problem.

To correct this problem follow these steps. Move your pointer to the Taskbar at the bottom of the screen and click your right mouse button to get a menu.



Shot of the Taskbar menu.

Click on “Properties” at the bottom of the menu and you will get a new menu so you can change settings for the Taskbar.




Screen shot of Taskbar And Start Menu Properties

Click on the box for “Auto-hide the taskbar” to select this option, then click “Apply”, then click “OK”. This will close the menu.


Now the Taskbar will disappear or hide when your pointer is not at the bottom of the screen. When you want to use the Taskbar move the pointer to the bottom of the screen and the Taskbar will appear.

If the control panel software is still open, close the program. Now open the control panel, make sure the pointer is above the Taskbar level and you should see the Enable Virtual and A-Axis boxes.



Screen shot after the fix showing the Enable boxes (lower left).

You can now enable the A-Axis and get the jog buttons in the control panel along with the set front and set rear options.



Screen shot with A-Axis enabled and Jog panel opened showing jog buttons for the A-axis and Set buttons for Rear and Front.